

Riddoch Highway Photo Log – Southern Overtaking Lane

Amenity Trees / Patches or Scattered Trees being trimmed or removed



Plate 10-1: Scattered Tree 9 (was S_1, centre by road, multi-stemmed)



Plate 10-2: Scattered Tree 10 (was S_2, DEAD) (centre by road)



Plate 10-3: Scattered tree 11 (was S_3) (centre)



Plate 10-4: Scattered tree 12 (was S_4) (centre)



Plate 10-5: Scattered tree 13 (was S_5) (centre)



Plate 10-6: Scattered tree 14 (was S_6) (centre)



Plate 10-7: Scattered tree 15 (was S_7) (centre)




Plate 10-8: Scattered tree 16 (was S_8)(left side, in front) of fence



Plate 10-9: Scattered tree 17 (was S_9) (centre, roadside)



Plate 10-10: Scattered tree 18 (was S_10) (centre, front by roadside)



Plate 10-11: Scattered trees (dead, not included in scattered tree sheet, S_11 in DIT sheet)(centre)



Plate 10-12: Scattered tree 19 (was S_12) (centre, multi-stemmed)



Plate 10-13: Scattered tree 20 (was S_13) (centre)



Plate 10-14: Scattered tree 21 (was S_14)(centre)



Plate 10-15: Scattered tree 22 (was S_15)(centre, foreground)



Plate 10-16: Scattered tree 23 (was S_16) (centre of photo next to Pine)



Plate 10-17: Scattered tree 24 (was S_17) (left side, front tree)



Plate 10-18: Scattered tree 25 (was S_18) (left side, rear tree)



Plate 10-19: Scattered tree 26 (was S_19)(centre)



Plate 10-20: Scattered tree 27 (was S_20)(centre)



Plate 10-21: Scattered tree 28 (was S_21) (centre, multi-stemmed)



Plate 10-22: Scattered tree 29 (was S_22)(centre left, multi-stemmed)



Plate 10-23: Scattered tree 30 (was S_23)(centre, right)



Plate 10-24: Scattered tree 31 (S_24) (centre)



Plate 10-25: Scattered tree 32 (was S_25) (90% dieback) (centre on fence line)



Plate 10-26: Scattered tree 33 (wasS_26)(centre)



Plate 10-27: Scattered tree 34 (was S_27)(centre)



Plate 10-28: Scattered trees (dead), original tree number S_28 (left), not on map, not in scattered tree sheet.



Plate 10-29: Scattered tree 35 (was S_29) (second from left)



Plate 10-30: Scattered tree 36 (was S_30) (middle)



Plate 10-31: Scattered tree (was S_31) (dead) (right), not on map, not in scattered tree sheet



Plate 10-32: Scattered tree 37 (was S_32)(left, multi-stemmed)



Plate 10-33: Scattered tree 38 (was S_33)(centre)



Plate 10-34: Scattered tree 39 (was S_34) (right, multi-stemmed)



Plate 10-35: Scattered tree 40 (was S_35)(centre)



Plate 10-36: Scattered tree 41 (was S_36)(centre)



Plate 10-37: Scattered tree 42 (was S_37)(centre)



Plate 10-38: Scattered tree 43 (was S_38)(centre)



Plate 10-39: Scattered tree 44 (was S_39)(centre)



Plate 10-40: Scattered tree clump C (was S_A) with Scattered tree 18 (was S_C) in foreground



Plate 10-41: Scattered tree clump D (was S_B)(as indicated above)



Plate 10-42: Scattered tree clump E (was S_C)(as indicated above)



Plate 10-43: Scattered tree clump F (was S_D)(as indicated above)



Plate 10-44: Scattered tree clump G (was S_E)(as indicated above)



Plate 10-45: Amenity patch 1 (S_AP1)(patch as shown above – all vegetation)



Plate 10-46: Amenity patch 2 (S_AP2) Layby. Facing south. All vegetation shown



Plate 10-47: Amenity tree 1 (S_AT1)(centre)



Plate 10-48: Amenity tree 2 (S_AT2)(centre) (sapling)



Plate 10-49: Amenity tree 3 (S_AT3)(centre)



Plate 10-50: Amenity tree 4 (S_AT4)(centre)



Plate 10-51: Amenity tree 5 (S_AT5)(centre)



Plate 10-52: Amenity tree 6 (S_AT6)(centre)